Industry 4.0: Data Analysis is Key for Optimizing the Shop Floor

Dr.-Ing. Benny Drescher
CTO at Hong Kong Industrial Artificial Intelligence and Robotics Centre (FLAIR)
July 8, 2021

Picture: www.geospatialworld.net

Lean Management helps to identify eight types of waste in a manufacturing and logistic operations.

Talent
Employees not leveraged to their potential

Inventory
Holding inventory (material and information) more than is required

Motion
Movement of people or information that does not add value

Waiting
Waiting for someone, information, or an event to happen

Transportation
Movement of items (or information) more than is required resulting in wasted efforts, energy, and cost

Defects
Errors, mistakes, and Rework

Overproduction
Processing more than required where a simple approach would have been sufficient

Overprocessing
Processing too soon or too much (than what is required)

The Smart Navigator for Industry 4.0 concentrates on creating business value for manufacturing companies.

FLAIR

Network

Data

Sensors

Smart Innovation

Smart Network

HMI

Smart Solution

New Digital Business Models

Smart Production

Mindset and Culture

Enablers

Application

Uniqueness

Strategy and Organization

Growth & Revenue

Value

Productivity & Efficiency

*Human Machine Interaction

Most important step is the visualization of the shop floor in real-time.

Picture: datapine.com

Online monitoring of printing machines enables novel services for scheduling maintenance at customers.

Picture: dpa, stuttgarter-zeitung.de

Source: usu.com, Heidelberger Druckmaschinen

The Manufacturing Execution System ToolScope of KOMET monitors machine and process status of CNC Machines.

Source: Komet Group

Thank you very much!